




EXTRA TRAY CLIP

Part# PTL-ETC

\$48.00ea




Cover Plate - 1 pc




3' Cable w/Stop - 1 pc




Base Plate w/Rubber - 1 pc



Cable Nut Plate w/Rubber - 4 pcs



Cable Lock w/Key - 1 pc



Glue - 2 pcs



Alcohol Swabs - 4 pcs





BACK VIEW

1. ADHERE BASE PLATE WITH BENDS AS SHOWN
2. ALIGN COVER PLATE TO THE KNOCK OUT HOLES UNTIL THEY ARE FLUSH
3. RUN SECURITY CABLE THROUGH THE HOLES IN THE BASE PLATE
4. RUN SECURITY CABLE THROUGH THE CABLE PLATE ON OTHER SIDE OF PRINTER
5. LOCK WITH PASS THROUGH OR CABLE LOCK




BASE PLATE W/ADHESIVE BACKING AND BENDS AT ENDS WITH A HOLE FOR SECURITY CABLE TO PASS THROUGH





SIDE VIEW



RUN SECURITY
CABLE THROUGH
CABLE NUTS

ATTACH CABLE PLATES
TO BOTH SIDES OF
PRINTER AS SHOWN.

CABLE PLATES WITH
CABLE NUT WELDED
ON TOP AND ADHESIVE
ON BACK

